

VIC 160 South Gippsland Highway Dandenong 3175

PO Box 4040 Dandenong South VIC 3164 Australia

Telephone: +61 3 8726 5566

EM: sterivic@steritech.com.au

5 Widemere Road Wetherill Park 2164

PO Box 6632 Wetherill Park NSW 2164 Australia

Telephone: +61 2 8785 4400

EM: sterinsw@steritech.com.au

180 Potassium Street Narangba 4504

PO Box 376 Burpengary QLD 4505 Australia

Telephone: +61 7 3293 1566

EM: steriqld@steritech.com.au

Telephone: +61 3 9216 3500

VIC 21 Titan Drive

Merrifield 3064

EM: mrforders@steritech.com.au

Annual EPL Ethylene Oxide Stack Emission Montoring

The annual results (reported in mg/m³) from the ethylene oxide emissions testing of the thermal oxidisers located at Steritech Wetherill Park, NSW are listed in the table below:

Report Date	EPL ID Point #1 – TO-1		EPL ID Point #2- TO-2	
	Sterilization Cycle*	EtO Release⁴	Sterilization Cycle*	EtO Release⁴
10 August 2022	<0.06	<0.04	<0.06	<0.04
6 October 2021	<0.07	<0.04	<0.05	<0.05
3 June 2020	<0.045	<0.038	<0.070	<0.027
22 May 2019	<0.054	<0.035	<0.073	<0.035

^{*} EtO limit of 3mg/m³ based on a sterilization cycle average stack concentration.

Please call +61 2 8785 4450 should you have any further queries or concerns in relation to any of the above information.

Regards,

Steritech Pty Ltd

EPA Licence No. 12902

5 Widemere Road

Wetherill Park NSW 2164

Australia

Lot 205 DP 709613

[•] EtO limit of 5mg/m³ based on one (1) hour average stack concentration.